




MASW 1D/2D PROCESSED IN 3D, ACQUIRED AND EXTENDED INSIDE THE DAMAGED BUILDING



Line 4 East view
On the side of the walls




0m local elevation reference



● Geotechnical Parameter Calculation

Interpretation Legend	
● VLS	Very Loose
● LS	Loose
● DLS	Loose to Medium dense
● MDS	Medium dense
● VDS	Dense to Very Dense
—	Average Upper Limit of Compact Ground



Line 8
South View
Obstacles (Wall)
on North Side
INSIDE THE
BUILDING

